

1. ITEM 3 SHOULD BE ORIENTED THE SAME AS THE MMI LOGO.
2. SET AND CHECK TEMPERATURE PER ES390.
3. THESE ITEMS ARE SUB-ASSEMBLIES ON SEPARATE DRAWINGS.
4. ITEMS SHOWN IN PARENTHESIS REFLECT QUANTITIES IN A LOCAL GROUP AND MAY NOT INDICATE TOTAL ASSEMBLY QUANTITIES.
5. HEATER SHALL PASS ALL ELECTRICAL SAFETY COMPLIANCE TESTS PER ES497 BEFORE INSTALLING ELECTRICAL SAFETY TEST LABEL.

McElroy Manufacturing Parts List

Part Number: T5008009 Obsolete & Replaced by T5078401 (PitBull 500 12-20IPS 240V Heater Assembly) ((10/2004-7/2021))



This Heater comes equipped with a 20AMP Twist-Lock Plug (NEMA L6-20P)

Part Number T5008009 Component List

Item	Component	Description	Quantity	Unit	Price
1	T5033701	PitBull 500 II 240V Heater Handle/Controller Assembly	1.0	EA	720.00
2	AT5008007	12" - 500mm Heater Butt Plate Kit	1.0	EA	1,061.00
3	8163133	Model T5008009 Part NO Label	1.0	EA	61.22
4	T5008003	Right Htr Body	1.0	EA	1,259.00
5	T5008004	Left Htr Body	1.0	EA	1,259.00
6	T5008005	Htr OD Spacer	1.0	EA	213.00
7	1852006	Heater I.d. Spacer	1.0	EA	108.00
8	T5008201	220V Mica/foil Htr Element	1.0	EA	1,017.00
9	1852011	Tapped Htr Guide Rod Sprt Bkt	2.0	EA	38.39
10	1852012	C'sunk Htr Guide Rod Sprt Bkt	2.0	EA	38.39
11	MAN00036	#10-32NFX7/8LG Fhscs SS	6.0	EA	0.40
12	1863102	Htr Terminal Enclosure Half	2.0	EA	50.38
13	1808102	Htr Gasket	1.0	EA	4.92
14	MKI00003	1X3/16 316SS 100OHM Plat Rtd	1.0	EA	59.44
15	MJK00002	2.5LG,150-650DEG F Thermometer	1.0	EA	47.64
16	MBA00004	#10-24NC Hex Nut Stl PL	4.0	EA	0.35
17	MBE00004	#10 Reg Splt Lck Washer Stl PL	4.0	EA	0.10
18	MAN00008	#10-24NCX1LG Shcs SS	4.0	EA	0.70
19	MAH00046	#10-24NCX1/2LG Shcs SS	8.0	EA	1.09
20	MAN00023	#8-32NCX5/16LG Shcs SS	25.0	EA	0.40
21	AT5008101	TracStar 500 Stripper Bar Kit	1.0	EA	302.00
22	T5008310	TracStar 500 II Heater Bag & Frame Assembly	1.0	EA	938.00
23	8163210	Electrical Safety Test Label	1.0	EA	0.00

Please visit <https://fusion.mcelroy.com/parts> to purchase parts or for more information.