APPRV'D: PJD DRAWN: RLT DATE: 4/30/18 McElroy Manufacturing, Inc. 2495501_5701_5901 BOC The leader by design. HEATER BAG ASSEMBLY Tulsa, Oklahoma U.S.A. NOTE: THIS DRAWING AND THE INFORMATION CONTAINED THEREIN IS THE CONFIDENTIAL AND PROPRIET ARY PROPERTY OF McEltoy Manufacturing, Inc. THE DRAWMEN IS NOT DE REPRODUCED IN ANY MANNER, SUBMITTED TO OUTSIDE PARTIES FOR EXAMINATION, OR USED DIRECTLY OR INDIRECTLY FOR THE PURPOSES OTHER THANTHOSE FOR WHICH IT WAS FURNISHED WITHOUT WRITTEN PERMISSION OF McElroy Manufacturing, Inc. NOTES: 1. APPLY MEDIUM STRENGTH THREAD RETAINING COMPOUND.



Click Here to View Item Online

| Part Number 2495901 Component List | | | | |
|------------------------------------|-----------|---|---------------|--------|
| ltem | Component | Description | Quantity Unit | Price |
| 1 | 2495301 | Guide Rod Pin (Effective to 11/5/18) | 2.0 EA | 0.00 |
| 2 | 2495401 | Heater Bag Guide Rod | 2.0 EA | 0.00 |
| 3 | 2496001 | 630MM Heater Bag Wld | 1.0 EA | 0.00 |
| 4 | 2496005 | 630MM Heater Panel | 2.0 EA | 564.00 |
| 5 | MAH00097 | 1/4-20NCX1/2LG Bhscs SS (Effective to 11/5/18) | 2.0 EA | 0.41 |
| 5 | MAC00463 | 3/8-16NCX4-1/4LG Shcs | 2.0 EA | 5.98 |
| 6 | MBG00031 | 1/4 Fender Washer Stl PL (Effective to 11/5/18) | 4.0 EA | 0.31 |
| 6 | MBF00007 | 3/8 TY 'a' Wide FL Wshr Stl PL | 4.0 EA | 0.11 |
| 7 | MJA00025 | Cam Handle (Effective to 11/5/18) | 2.0 EA | 0.00 |
| 7 | MJA00027 | Eccentric Cam Clamping Lever | 2.0 EA | 43.43 |

