





McElroy Manufacturing, Inc.

The leader by design.

Tulsa, Oklahoma U.S.A.

DRAWN: ERA

CHECK: PJD

APPRVD: JAL

DATE: 03/14/12

SHT No: 1B





REV No: H

PART No: 238501

16mm-63mm SOCKET HEATER ASSEMBLY 100-120V, 50/60 Hz, 1 Ph

NOTE: THIS DRAWING AND THE INFORMATION CONTAINED THEREIN IS THE CONFIDENTIAL AND PROPRIETARY PROPERTY OF McElroy Manufacturing, Inc. THE DRAWING IS NOT TO BE REPRODUCED IN ANY MANNER, SUBMITTED TO OUTSIDE PARTIES FOR EXAMINATION, OR USED DIRECTLY OR INDIRECTLY FOR THE PURPOSES OTHER THAN THOSE FOR WHICH IT WAS FURNISHED WITHOUT WRITTEN PERMISSION OF McElroy Manufacturing, Inc.

120 VAC PLUG



## McElroy Manufacturing Parts List

**Part Number:** 238501 Obsolete & Replaced by 253101 (16mm-63mm 120V Socket Heater Assembly)



### 16mm-63mm 120V Socket Heater Assembly

#### Part Number 238501 Component List

Item	Component	Description	Quantity	Unit	Price
1	238601	16-63MM Socket Heater Body	1.0	EA	148.00
2	238701	Cover Plate Gasket	2.0	EA	5.65
3	238801	Heater Handle Wld	1.0	EA	89.67
4	434201	Replaced by A434202 (Effective to 4/26/17)	1.0	EA	0.00
4	434202	13AMP/120V Power Cord	1.0	EA	42.08
5	437203	Small Htr Handle/enclosure	1.0	EA	30.34
6	816382	Temperature Scale Label (Effective to 9/17/12)	1.0	EA	6.85
6	8163207	Temperature Set Label	1.0	EA	8.35
7	8163205	Model 238501 Part No. Label	1.0	EA	6.32
8	A424901	14 MultiMc/Socket Fusion Heater Screw&Driver Kit	1.0	EA	48.36
9	T5030001	Heater Control Pcb Assy	1.0	EA	149.00
10	T5030002	Potentiometer Assy	1.0	EA	14.08
11	T5030104	Heater Control Knob Cover	1.0	EA	9.36
12	MAH00036	#6-32NCX3/8LG Hwh TC Scr (Effective to 6/13/17)	1.0	EA	0.35
12	MAL00024	#8-32NCX1/4LG Hwhsms SS	1.0	EA	0.34
13	MAH00046	#10-24NCX1/2LG Shcs SS (Effective to 11/7/13)	2.0	EA	1.09
13	MAC00038	#10-24NCX3/4LG Shcs SS	2.0	EA	0.48
14	MAL00010	#6-19X3/4LG Torx T15 Pan Hdscr	4.0	EA	0.55
15	MAL00011	#6-19X1/4LG Torx T15 Pan Hdscr	1.0	EA	0.64

## McElroy Manufacturing Parts List

**Part Number:** 238501 Obsolete & Replaced by 253101 (16mm-63mm 120V Socket Heater Assembly)

16	MAL00013	#6-19X1/2LG Torx T15 Pan Hdscr	2.0 EA	0.48
17	MBA00067	3/8-32NEF X 0.22 X 1/4 Sealnut	1.0 EA	4.08
18	MDL00243	.070DIA Buna-n O-ring Stock	1.5 FT	0.96
19	MDL00248	O-ring	2.0 EA	0.69
20	MJJ00023	Control Knob	1.0 EA	4.86
21	MKI00003	1X3/16 316SS 100OHM Plat Rtd	1.0 EA	59.44
22	MLD00089	120V,350W,1/2X5 Crtg Heater	2.0 EA	63.46
23	MLL00004	#18 Type Tggt Elec Wire (Effective to 8/29/16)	1.0 FT	2.42
23	MLL00214	#18 Type Tggt Wire, Green/yel	1.0 FT	1.65
24	MLM00002	2/16-2/22 Closed End Splice	1.0 EA	0.79
25	MLM00004	18-22 X #6 Ring Term, Non-insu (Effective to 6/13/17)	1.0 EA	0.96
25	MLM00372	18-22 X #8 Hi-temp Ring Term	1.0 EA	1.18
26	MLN00219	Fiberglass Tape (per Ft)	0.666 FT	0.52
27	8163210	Electrical Safety Test Label	1.0 EA	0.00
28	434302	Power Cord Strain Relief	1.0 EA	13.79

Please visit <https://fusion.mcelroy.com/parts> to purchase parts or for more information.

UNCLASSIFIED