	McElroy Manufacturing, Inc.	DRAWN: LBK	MEP APP	^{RV'D:} DWP	DATE:	9/6/06	SHT 1 REV PART T2409101					
MULESS (3) PLC. DIMS .XXX = ±0.005" ANGULAR DIMS = ±1/4° REMOVE ALL BURRS STAMP OR ETCH P/N ON ALL DETAIL PARTS 1 1 WELDMENT	The Diverse of the Andrewski Constraint of the Andrewski C											
Image: With the second seco												
INLESS (3) PLC. DIM'S .XXX = ±0.005" ANGULAR DIM'S = ±1/4° NOTED (2) PLC. DIM'S .XXX = ±0.010" REMOVE ALL BURRS ON ALL DETAIL PARTS							AIING PANEL					
VOTED (2) PLC. DIM'S XX = ±0.010" REMOVE ALL BURRS STAMP OR EICH PIN REMOVE ALL BURRS ALL DETAIL PARTS		1/40		1 1	1							
THERWISE- FRACTIONAL DIM'S = ±1/32" BREAK ALL SHARP EDGES CHARLED AND MINIMABER TEM QTY. SIZE AND DESCRIPTION	NOTED (2) PLC. DIM'S XX = +0.010" REMOVE ALL BU			ER ITEM	QTY.	ASSEMBLY						



	Click Here to View Item Onlin									
	McElroy Manufacturing Parts List									
Part I	Number: T2409101	Replaced by T2423001 (TracStar 630 In Ditch H	Heater / Facer Storage Rack	Assembly) (9/	2006 - 10/2018)					
Part Number T2409101 Component List										
Item	Component	Description	Quantity	Unit	Price					
1	T2409201	Obsolete	1.0	EA	0.00					
2	2427413	Heater Insulating Panel	1.0	EA	1,624.00					
3	2427414	Heater Insulating Panel	1.0	EA	1,624.00					
Pleas	e visit https://fusion.r	ncelroy.com/parts to purchase parts or for more	information.							

