


LARGE HEATER HANDLE SUBASSEMBLY

NOTE: THIS DRAWING AND THE INFORMATION CONTAINED THEREIN IS THE CONFIDENTIAL AND PROPRIETARY PROPERTY OF McEroy Manufacturing, Inc. THE DRAWING IS NOT TO BE REPRODUCED IN ANY MANNER, SUBMITTED TO OUTSIDE PARTIES FOR EXAMINATION, OR USED DIRECTLY OR INDIRECTLY FOR THE PURPOSES OTHER THAN THOSE FOR WHICH IT WAS FURNISHED WITHOUT WRITTEN PERMISSION OF McEroy Manufacturing, Inc.

NOTES:

1. TORQUE TO 5 IN-LBS.
2. TORQUE TO 23 IN-LBS.
3. APPLY THIN LAYER OF HTRC COMPOUND TO TRIAC ON BACK SIDE OF THE PCB.
4. PREASSEMBLE THESE COMPONENTS BEFORE SHIPPING



McElroy Manufacturing Parts List

Part Number: T5033401 Large Heater Handle Subassembly

Part Number T5033401 Component List

Item	Component	Description	Quantity	Unit	Price
1	437401	Heat Sink Gasket	1.0	EA	0.00
2	T5030006	Heater Control Pcb Assy (Effective to 12/13/20)	1.0	EA	0.00
2	T5030009	Heater Control Pcb Assy	1.0	EA	0.00
3	T5030108	Heater Handle/enclosure	1.0	EA	0.00
4	MAH00296	#6-32X1/4 Phil Pan Sealg Scr	1.0	EA	2.00
5	MAL00010	#6-19X3/4LG Torx T15 Pan Hdscr	4.0	EA	0.56
6	MAL00031	#6-19X1-1/2'LG Torx T15 Panscr	2.0	EA	0.24
7	MAL00034	#6-19X1/4LG Phil Pan Hdscr	2.0	EA	0.06
8	MAL00035	#6-19X3/8LG Phil Pan Hdscr	4.0	EA	0.08
9	MDL00373	.040DIA Buna O-ring Cord Stock	1.74	FT	1.81
10	MQI00111	Heatsink	1.0	EA	0.00

Please visit <https://fusion.mcelroy.com/parts> to purchase parts or for more information.