



McElroy Manufacturing, Inc.

The leader by design.

Tulsa, Oklahoma U.S.A.

DRAWN:

RLE

CHECK:

BLM

APPR'VD:

DWP

DATE:

4/25/05

SHT

No:

1

REV

No:

D

PART

No:


T1810901

EP1500P (Pit Bull®) HPU ASSEMBLY 240V, 60Hz, 1Ph

NOTE: THIS DRAWING AND THE INFORMATION CONTAINED THEREIN IS THE CONFIDENTIAL AND PROPRIETARY PROPERTY OF McElroy Manufacturing, Inc. THE DRAWING IS NOT TO BE REPRODUCED IN ANY MANNER, SUBMITTED TO OUTSIDE PARTIES FOR EXAMINATION, OR USED DIRECTLY OR INDIRECTLY FOR THE PURPOSES OTHER THAN THOSE FOR WHICH IT WAS FURNISHED WITHOUT WRITTEN PERMISSION OF McElroy Manufacturing, Inc.

NOTES:

1. ITEMS SHOWN IN PARENTHESIS REFLECT QUANTITIES IN A LOCAL GROUP AND MAY NOT INDICATE TOTAL ASSEMBLY QUANTITIES.
2. SEE DRAWING T1806901 HYDRAULIC SCHEMATIC ITEM 1 FOR LAYOUT AND COMPONENTS.
3. SEE DRAWING T1807001 PLUMBING SCHEMATIC ITEM 2 FOR LAYOUT AND COMPONENTS.
4. SEE DRAWING T1811601 ELECTRICAL POWER ASSEMBLY ITEM 3 FOR LAYOUT AND COMPONENTS.



McElroy Manufacturing Parts List

Part Number: T1810901 EP1500P (Pit Bull) HPU Assembly 240V, 60Hz, 1Ph

Part Number T1810901 Component List

Item	Component	Description	Quantity	Unit	Price
1	T1806901	EP1500P (PitBull) HPU Hydraulic Schematic	1.0	EA	0.00
2	T1807001	EP1500P (PitBull) HPU Plumbing Schematic	1.0	EA	0.00
3	T1811601	EP1500P (PitBull) HPU 240V,60Hz,1Ph Electrical Power Assembly	1.0	EA	8,042.00
4	T1811701	EP1500P (Pit Bull®) HPU Cart Assembly	1.0	EA	0.00
5	T5034102	PitBull Fusion Machine Operator's Manual	1.0	EA	167.00
6	1219105	25ft Extension Hose Set (4 hoses)	1.0	ST	995.00
7	816342	Safety Instr Manual Label	1.0	EA	4.90
8	8163106	Hyd Oil Specification Label	1.0	EA	10.00
9	8163119	Medium McElroy Branding Label	2.0	EA	10.00
10	MAB00031	5/16-18NCX1/2LG Hhcs	4.0	EA	0.42
11	MAB00081	1/2-13NCX1-1/4LG Hhcs	4.0	EA	1.40
12	MAL00007	1/4-20NCX3/4LG Hwh TF Screw	3.0	EA	1.01
13	MBA00009	1/2-13NC Fhsh Hex Nut Stl PL	4.0	EA	0.45
14	MBE00006	5/16 Reg Splt Lck Wshr Stl PL	4.0	EA	0.11
15	MBE00009	1/2 Reg Splt Lck Washer Stl PL	4.0	EA	0.16
16	MBF00009	1/2 TY 'a' Wide FL Wshr Stl PL	4.0	EA	0.23
17	MBG00031	1/4 Fender Washer Stl PL (Effective 2/7/05 to 10/23/13)	3.0	EA	0.31
17	MBF00005	1/4 TY 'a' Wide FL Wshr Stl PL	3.0	EA	0.11
18	MJQ00259	Standard 9x6 Literature Compartment	1.0	EA	58.39
19	T1811901	EP1500P (PitBull) HPU Lifting Sling	1.0	EA	233.00

Please visit <https://fusion.mcelroy.com/parts> to purchase parts or for more information.