



Click Here to View Item Online

Please visit https://fusion.mcelroy.com/parts to purchase parts or for more information.

Part Number: ASW10301 Sidewinder Chain Clamp Assembly Part Number ASW10301 Component List				
1	A213601	Sidewinder/2/14/28 Tailstock Chain Assembly	2.0 EA	35.24
2	A829001	Short Clamp Knob Assembly	2.0 EA	86.7
3	MAC00035	#10-24NCX3/8LG Shcs PL	2.0 EA	0.48
4	MCK00027	3/8DIAX2-3/4LG Lck Pin Stl PL	4.0 EA	4.52
5	SW01601	Roller	2.0 EA	13.55
6	SW01901	Chain Take-up Attachment	2.0 EA	117.00
7	SW02101	Compression Spring	2.0 EA	4.70
8	SW03401	SW Htr Guide	1.0 EA	69.34
9	SW05703	Tailstock	1.0 EA	467.00
10	401701	Chain Hook	2.0 EA	44.8
11	MBG00012	3/8 Flat Washer Stl	2.0 EA	1.93

