

- 1 -



			Click Here to	View Item Online
McElroy Manufacturing Parts List				
Part I	Number: AT1807401	HC Obsolete & Replaced by At1830001HC (TracStar 61)	8 Hydraulic Clamping MF Fusion M	/lachine Package)
Part I	Number AT1807401H	C Component List		
Item	Component	Description	Quantity Unit	Price
1	AT1816501	Obsolete & Replaced by AT1830101	1.0 EA	0.00
2	AT1807501HC	PitBull 618 Hydraulic Clamping MF Fusion Machine Package	1.0 EA	0.00
Pleas	e visit https://fusion.mo	celroy.com/parts to purchase parts or for more informatio	n.	

Γ

May 8, 2024 4:19:56 PM CDT

