



McElroy Manufacturing Parts List

Part Number: CTS20001 Obsolete & Replaced by CTS24301 (1LC 240V Heater Assembly)

Part Number CTS20001 Component List

Item	Component	Description	Quantity	Unit	Price
1	1854801	Replaced by A1854802 (Effective to 8/23/17)	1.0	EA	0.00
1	1854802	15A,250V Power Cord Assy w/ Nema 6-15 Plug	1.0	EA	65.04
2	816382	Temperature Scale Label	1.0	EA	6.85
3	CTS20901	Heater Body	1.0	EA	208.00
4	CTS20701	Enclosure	1.0	EA	584.00
5	T5030001	Heater Control Pcb Assy	1.0	EA	149.00
6	T5030002	Potentiometer Assy	1.0	EA	14.08
7	MAH00042	#8-32NCX1/2LG Shcs SS	1.0	EA	0.98
8	MAH00093	#4-40NCX3/16LG Lock Scr (Effective to 1/27/15)	1.0	EA	0.29
8	MAE00122	#4-40NCX1/4LG Bhscs SS (Effective 1/28/15 to 4/8/19)	1.0	EA	0.00
8	MAE00008	#6-32NCX1/4LG Bhscs PL	1.0	EA	0.98
9	MBA00067	3/8-32NEF X 0.22 X 1/4 Sealnut	1.0	EA	4.08
10	MJJ00023	Control Knob	1.0	EA	4.86
11	MJK00002	2.5LG,150-650DEG F Thermometer	1.0	EA	47.64
12	MKI00003	1X3/16 316SS 100OHM Plat Rtd	1.0	EA	59.44
13	MLD00087	120V,50W,1/4X1.5 Crtg Heater	2.0	EA	90.48
14	MLM00002	2/16-2/22 Closed End Splice	2.0	EA	0.79
15	MLM00004	18-22 X #6 Ring Term, Non-insu	1.0	EA	0.96
16	MLN00219	Fiberglass Tape (per Ft)	0.666	FT	0.52
17	MCG00017	1/8DIA X3/4LG Roll Pin	2.0	EA	0.38
18	CTS20801	Heater Handle Wld	1.0	EA	0.00
19	437203	Small Htr Handle/enclosure	1.0	EA	30.34
20	8163182	Model CTS20001 Part NO Label	1.0	EA	28.15
21	MAL00010	#6-19X3/4LG Torx T15 Pan Hdscr	4.0	EA	0.55
22	MAL00011	#6-19X1/4LG Torx T15 Pan Hdscr	1.0	EA	0.64
23	MAL00013	#6-19X1/2LG Torx T15 Pan Hdscr	2.0	EA	0.48
24	MDL00243	.070DIA Buna-n O-ring Stock	1.5	FT	0.96
25	MDL00248	O-ring	2.0	EA	0.69
26	MLL00004	#18 Type Tggt Elec Wire (Effective to 8/29/16)	1.0	FT	2.42
26	MLL00214	#18 Type Tggt Wire, Green/yel	1.0	FT	1.65
27	434302	Power Cord Strain Relief	1.0	EA	13.79

Please visit <https://fusion.mcelroy.com/parts> to purchase parts or for more information.