CHECK: APPRV'D: DATE: 11/19/04 DWG No: SHT No: 1 REV No: PART No: McElroy Manufacturing, Inc. SRB TABULATED BWW MLM TP-300 The leader by design. CAD No: TEST CAP ASSEMBLY TP-300 Tulsa, Oklahoma U.S.A. NOTE: THIS DRAWING AND THE INFORMATION CONTAINED THEREIN IS THE CONFIDENTIAL AND PROPRIETARY PROPERTY OF MEEIROY Manufacturing, Inc. THE DRAWING IS NOT TO BE REPRODUCED IN ANY MANNER, SUBMITTED OUTSIDE PARTIES FOR EXAMINATION, OR USED DIRECTLY FOR INDIRECTLY FOR THE PURPOSES OTHER THAN THOSE FOR WHICH IT WAS FURNISHED WITHOUT WRITTEN PERMISSION OF MEEIROY Manufacturing, Inc. NOTES: 1. PARTS FOR 2" IPS ONLY. 6(2) < 1 0 2 (4ea) (3) PLC. DIM'S .XXX = ± 0.005 " (2) PLC. DIM'S .XX = ± 0.010 " FRACTIONAL DIM'S = $\pm 1/32$ " ANGULAR DIM'S = $\pm 1/4$ '
REMOVE ALL BURRS
BREAK ALL SHARP EDGES UNLESS NOTED STAMP OR ETCH P/N ON ALL DETAIL PARTS OTHERWISE: MMI NUMBER ITEM SIZE AND DESCRIPTION



Click Here to View Item Online

McElroy Manufacturing Parts List

Part Number: TP-310 2IPS Test Cap Assembly

Part Number TP-310 Component List				
ltem	Component	Description	Quantity Unit	Price
1	TP-410	2IPS Test Cap Housing	1.0 EA	0.00
2	TP-610	2IPS Test Cap Locking Ring	4.0 EA	21.72
3	TP-704	2IPS TC Compression Spring	1.0 EA	17.90
4	MDL00176	Buna-n 70 Duro O-ring	1.0 EA	0.93
5	TP-501	Test Cap Handle	1.0 EA	27.12
6	MJJ00011	Black Flat Vinyl Hand Grip	2.0 EA	2.49
7	MAN00014	1/4-20NCX1/2LG Fhscs SS	2.0 EA	1.08
8	TP-1201	Test Cap Warning Label	1.0 EA	7.70
9	TP-1110	2 IPS Test Cap Lanyard Assembly	1.0 EA	79.75
 Pleas	e visit https://fusion.n	ncelroy.com/parts to purchase parts or for more inform	nation.	

