


NOTE: THIS DRAWING AND THE INFORMATION CONTAINED THEREIN IS THE CONFIDENTIAL AND PROPRIETARY PROPERTY OF McElroy Manufacturing, Inc. THE DRAWING IS NOT TO BE REPRODUCED IN ANY MANNER, SUBMITTED TO OUTSIDE PARTIES FOR EXAMINATION, OR USED DIRECTLY OR INDIRECTLY FOR THE PURPOSES OTHER THAN THOSE FOR WHICH IT WAS FURNISHED WITHOUT WRITTEN PERMISSION OF McElroy Manufacturing, Inc.



McElroy Manufacturing Parts List

Part Number: AT1213002 PitBull 412 HF Fusion Machine Package

Part Number AT1213002 Component List

Item	Component	Description	Quantity	Unit	Price
1	T1200402	TracStar 412 HF Carriage Assembly	1.0	EA	0.00
2	T1200501	TracStar 412 Facer Assembly	1.0	EA	9,162.00
3	1242112	Obsolete & Replaced by 1284501 (Effective 2/9/04 to 2/9/20)	1.0	EA	0.00
3	1284501	412 220-240V,50/60Hz,1Ph Heater Assembly	1.0	EA	5,175.00
4	MJQ00259	Standard 9x6 Literature Compartment	1.0	EA	58.39
5	MAE00032	1/4-20NCX5/8LG Bhscs	3.0	EA	0.41
6	MBG00031	1/4 Fender Washer Stil PL (Effective 10/4/07 to 10/23/13)	4.0	EA	0.31
6	MBF00005	1/4 TY 'a' Wide FL Wshr Stil PL	3.0	EA	0.11
7	MBH00043	1/4-20NC Low Crown Acorn Nut	3.0	EA	0.48
8	816342	Safety Instr Manual Label	1.0	EA	4.90

Please visit <https://fusion.mcelroy.com/parts> to purchase parts or for more information.