



APPR√D: DRAWN: CHECK: McElroy Manufacturing, Inc. 1B SO5501 DWP FAW JAL 3/19/10 The leader by design SIDE BEND TEST FIXTURE ASSEMBLY Tulsa, Oklahoma U.S.A. NOTE: THIS DRAWING AND THE INFORMATION CONTAINED THEREIN IS THE CONFIDENTIAL AND PROPRIETARY **INSTRUCTIONS:** PROPERTY OF McElroy Manufacturing, Inc. THE DRAWING IS NOT TO BE REPRODUCED IN ANY MANNER, SUBMITTED TO OUTSIDE PARTIES FOR EXAMINATION, OR USED DIRECTLY OR INDIRECTLY FOR THE PURPOSES OTHER 1. REMOVE PLUG FROM PUMP END AND DISCARD. THANTHOSE FOR WHICH IT WAS FURNISHED WITHOUT WRITTEN PERMISSION OF McElroy Manufacturing, Inc. 2. INSTALL ADAPTER AND ORIENT AS SHOWN. 3. INSTALL GAUGE AND ORIENT AS SHOWN. 4. INSTALL HOSE. 5. AFTER ASSEMBLY CONNECT TO TESTER AND EXTEND AND RETRACT CYLINDER SEVERAL TIMES TO PURGE AIR. 6. DISCONNECT PUMP AND HOSE ASSEMBLY FROM CYLINDER AND INSTALL CAPS FOR SHIPPING. ALL PARTS SHOWN ARE PART OF ITEM 13 -INSTALL WITH TEFLON TAPE ATTACH TO CYLINDER



Part Number S05501 Component List				
ltem	Component	Description	Quantity Unit	Price
1	S05601	Side Plate	2.0 EA	710.00
2	S05701	Channel	1.0 EA	0.00
3	S05801	Pin	2.0 EA	0.00
4	S05901	Pusher	1.0 EA	160.00
5	S06001	Brace	2.0 EA	0.00
6	S06101	1" Ram Assy	1.0 EA	392.00
7	MAB00003	1/4-20NCX3/4LG Hhcs	12.0 EA	0.31
8	MAN00085	1/2-13NCX3/4LG Fhscs SS	1.0 EA	0.00
9	MBA00007	3/8-16NC Fnsh Hex Nut Stl PL	2.0 EA	0.28
10	MBE00005	1/4 Reg Splt Lck Washer Stl PL	12.0 EA	0.10
11	MCG00046	3/16DIAX3/4LG Coiled Sprng Pin	6.0 EA	0.00
12	MDM00410	Steel Needle Roller Bearing	4.0 EA	17.74
13	MEB00164	Cylinder and Pump Set	1.0 EA	2,800.00
14	MJQ00469	One Piece Clamp-on Collar	4.0 EA	14.36
15	S06201	Thread Reducer	1.0 EA	0.00
16	8163118	Small McElroy Branding Label	2.0 EA	4.80
17	MDL00050	0.75 ID X 0.999 OD 7410 Wiper	8.0 EA	10.07
18	MAH00093	#4-40NCX3/16LG Lock Scr	4.0 EA	0.29
19	S07201	Bend Angle Label	2.0 EA	14.17
20	S07202	Bend Angle Label	2.0 EA	14.17

