


# PitBul® 28 BUTT FUSION MACHINE PACKAGE

NOTE: THIS DRAWING AND THE INFORMATION CONTAINED THEREIN IS THE CONFIDENTIAL AND PROPRIETARY PROPERTY OF McElroy Manufacturing, Inc. THE DRAWING IS NOT TO BE REPRODUCED IN ANY MANNER, SUBMITTED TO OUTSIDE PARTIES FOR EXAMINATION, OR USED DIRECTLY OR INDIRECTLY FOR THE PURPOSES OTHER THAN THOSE FOR WHICH IT WAS FURNISHED WITHOUT WRITTEN PERMISSION OF McElroy Manufacturing, Inc.



## McElroy Manufacturing Parts List

**Part Number:** AT805505 PitBull 28 HF Butt 120V Fusion Machine Package

### Part Number AT805505 Component List

| Item | Component | Description                                              | Quantity | Unit | Price    |
|------|-----------|----------------------------------------------------------|----------|------|----------|
| 1    | T800401   | TracStar 28 HF Butt Carriage Assembly                    | 1.0      | EA   | 0.00     |
| 2    | T800501   | TracStar 28 Facer Assembly                               | 1.0      | EA   | 6,276.00 |
| 3    | 848709    | Obsolete & Replaced by 901601 (Effective to 2/9/20)      | 1.0      | EA   | 0.00     |
| 3    | 901601    | 28 DIPS 100-120V,50/60Hz Heater Assembly                 | 1.0      | EA   | 4,160.00 |
| 4    | MJQ00259  | Standard 9x6 Literature Compartment                      | 1.0      | EA   | 58.39    |
| 5    | MAE00032  | 1/4-20NCX5/8LG Bhscs                                     | 4.0      | EA   | 0.41     |
| 6    | MBF00005  | 1/4 TY 'a' Wide FL Wshr Stil PL                          | 4.0      | EA   | 0.11     |
| 6    | MBG00031  | 1/4 Fender Washer Stil PL (Effective 10/4/07 to 9/28/11) | 4.0      | EA   | 0.31     |
| 7    | MBH00043  | 1/4-20NC Low Crown Acorn Nut                             | 4.0      | EA   | 0.48     |
| 8    | 816342    | Safety Instr Manual Label                                | 1.0      | EA   | 4.90     |

Please visit <https://fusion.mcelroy.com/parts> to purchase parts or for more information.