



McElroy Manufacturing, Inc.

The leader by design.

Tulsa, Oklahoma U.S.A.

DRAWN:

TGW

CHECK:

TLW

APPR'D:

SWB

DATE:

11/19/98

SHT

No: 6

REV

No: K

PART


No: 220200

4" HOT TAPPING TOOL ASSEMBLIES

NOTE: THIS DRAWING AND THE INFORMATION CONTAINED THEREIN IS THE CONFIDENTIAL AND PROPRIETARY PROPERTY OF McElroy Manufacturing, Inc. THE DRAWING IS NOT TO BE REPRODUCED IN ANY MANNER, SUBMITTED TO OUTSIDE PARTIES FOR EXAMINATION, OR USED DIRECTLY OR INDIRECTLY FOR THE PURPOSES OTHER THAN THOSE FOR WHICH IT WAS FURNISHED WITHOUT WRITTEN PERMISSION OF McElroy Manufacturing, Inc.

NOTES:

1. ITEM 5 NOT SHOWN.



McElroy Manufacturing Parts List

Part Number: 220207 4IPS High Density 3408/4710 Hot Tapping Tool Assembly

Part Number 220207 Component List

| Item | Component | Description | Quantity | Unit | Price |
|------|-----------|---|----------|------|----------|
| 1 | 22120507 | 4IPS High Density 3408/4710 Hot Tapping Tool Gland Fitting Assembly | 1.0 | EA | 1,172.00 |
| 2 | 221702 | 3-3/8L X 3D Toothed Cutter | 1.0 | EA | 1,183.00 |
| 3 | 221402 | 4IPS Htt Shaft | 1.0 | EA | 736.00 |
| 4 | 220701 | Htt Bearing Housing | 1.0 | EA | 199.00 |
| 5 | 226101 | 2,3&4 Htt Box W/foam Inserts (Effective 3/4/09 to 1/13/21) | 1.0 | EA | 563.00 |
| 5 | 251601 | Htt Box W/foam Inserts | 1.0 | EA | 636.00 |
| 6 | 224101 | Collar Mod | 1.0 | EA | 96.95 |
| 9 | MCB00003 | Ext Snap Ring | 2.0 | EA | 0.40 |
| 10 | MCA00007 | 1.625 Int Snap Ring | 1.0 | EA | 1.34 |
| 11 | MDM00028 | Ball Bearing | 1.0 | EA | 40.65 |
| 12 | MAH00091 | 1/4-20NCX1/2LG Hhcs | 1.0 | EA | 1.08 |
| 13 | MBG00025 | 3/8 Thrust Washer | 1.0 | EA | 5.39 |
| 14 | MBF00005 | 1/4 TY 'a' Wide FL Wshr Stil PL | 1.0 | EA | 0.11 |
| 15 | MJL00005 | 1/2 Drive Ratchet Wrench | 1.0 | EA | 198.00 |
| 16 | MJL00006 | 7/8 Socket X 1/2 Drive | 1.0 | EA | 36.47 |

Please visit <https://fusion.mcelroy.com/parts> to purchase parts or for more information.