

McElroy Manufacturing Parts List

Part Number: AT9000105 TracStar 900 Coach MF Fusion Machine Package (Obsolete)

Part Number AT9000105 Component List

Item	Component	Description	Quantity	Unit	Price
1	T9000105	TracStar 900 Coach MF Fusion Machine Assembly	1.0	EA	0.00
2	3616301	1236 Facer Assembly	1.0	EA	39,145.00
3	3617401	1236 Butt Plate Heater Assembly	1.0	EA	21,052.00

Please visit <https://fusion.mcelroy.com/parts> to purchase parts or for more information.

