


HEATER BAG FRAME ASSEMBLY

NOTE: THIS DRAWING AND THE INFORMATION CONTAINED THEREIN IS THE CONFIDENTIAL AND PROPRIETARY PROPERTY OF McElroy Manufacturing, Inc. THE DRAWING IS NOT TO BE REPRODUCED IN ANY MANNER, SUBMITTED TO OUTSIDE PARTIES FOR EXAMINATION, OR USED DIRECTLY OR INDIRECTLY FOR THE PURPOSES OTHER THAN THOSE FOR WHICH IT WAS FURNISHED WITHOUT WRITTEN PERMISSION OF McElroy Manufacturing, Inc.

NOTES:

1. APPLY MEDIUM STRENGTH THREAD LOCKER.



McElroy Manufacturing Parts List

Part Number: T560P0931924 Heater Bag Frame Assembly

Part Number T560P0931924 Component List

Item	Component	Description	Quantity	Unit	Price
1	T560P0932129	Insulation Plate	2.0	EA	218.00
2	T560P0934808	Rain Guard Top	1.0	EA	0.00
3	T560P0937850	Heater Bag Frame Wld	1.0	EA	1,634.00
4	T560P0948552	Htr Bag Frame Handle Stwng Wld	1.0	EA	0.00
5	T900P0887341	Heater Handle Pin	1.0	EA	85.78
6	MAB00002	1/4-20NCX1/2LG Hhcs	32.0	EA	0.18
7	MAB00033	5/16-18NCX1LG Hhcs	2.0	EA	0.42
8	MAB00064	3/8-16NCX1LG Hhcs (Effective to 6/3/24)	4.0	EA	0.51
8	MAB00065	3/8-16NCX1-1/4LG Hhcs	4.0	EA	0.52
9	MBA00006	5/16-18NC Fnsh Hex Nut Stl PL	2.0	EA	0.33
10	MBC00007	3/8-16NC Fnsh Hex Nyl Lck Nut	4.0	EA	0.39
11	MBF00005	1/4 TY 'a' Wide FL Wshr Stl PL	32.0	EA	0.11
12	MBG00048	5/16 Type 'an' Flat Washer SS	4.0	EA	2.44
13	MBH00127	1/4-20NC Weldnut Rnd Base PL	32.0	EA	0.56
14	MCH00021	3/4DIA X 11/16LG Hair Pin	1.0	EA	1.98
15	MCK00114	1/4DIA X 1/2 Grip Blind Rivet (Effective to 11/28/23)	8.0	EA	0.00
15	MCK00013	3/16DIA X 1/4 Grip Blind Rivet (Effective 11/29/23 to 1/16/25)	14.0	EA	0.24
15	MCLP1044862	3/16X.188/.250 Dom HD Rivet SS	14.0	EA	0.00
16	MJJ00084	3/4" Black Hand Grip	1.0	EA	10.08
17	MJQ00683	25MM OD 10MM LG C'brd Bumper	12.0	EA	30.65
18	MJQ00507	6"X4" Caution Hot Label	2.0	EA	22.44

Please visit <https://fusion.mcelroy.com/parts> to purchase parts or for more information.