


JAW CLAMP SYNCHRONIZATION MANIFOLD ASSEMBLY

NOTE: THIS DRAWING AND THE INFORMATION CONTAINED THEREIN IS THE CONFIDENTIAL AND PROPRIETARY PROPERTY OF McElroy Manufacturing, Inc. THE DRAWING IS NOT TO BE REPRODUCED IN ANY MANNER, SUBMITTED TO OUTSIDE PARTIES FOR EXAMINATION, OR USED DIRECTLY OR INDIRECTLY FOR THE PURPOSES OTHER THAN THOSE FOR WHICH IT WAS FURNISHED WITHOUT WRITTEN PERMISSION OF McElroy Manufacturing, Inc.

NOTES:

1. ORIENT VALVES AND FITTINGS APPROXIMATELY AS SHOWN.
2. LUBRICATE HYDRAULIC FITTINGS THREADS AND O-RING BEFORE ASSEMBLY.
3. TORQUE VALUES LISTED ARE MINIMUM, TOLERANCE -0/ +10%.
4. REPLACEMENT VALVES AND TORQUE SPECIFICATIONS:
 - MELP0991148 [30 ft-lb]
 - MFLP0989097 [3 T.F.F.T.]T.F.F.T. = TURNS FROM FINGER TIGHT. FINGER TIGHTEN THE FITTING OR SLIGHTLY TIGHTEN WITH ALLEN WRENCH THEN TIGHTEN 3 FULL TURNS.



McElroy Manufacturing Parts List

Part Number: T560P0991132 Jaw Clamp Synchronization Manifold Assembly

Part Number T560P0991132 Component List

Item	Component	Description	Quantity	Unit	Price
1	MELP0990742	Jaw Clamp Syncro Manifold	1.0	EA	0.00
2	MFQ00039	4MSL/4MSAE Adapter	2.0	EA	6.94
3	MFQ00067	4MSL/4MSAE 45DEG Elbow	4.0	EA	16.86

Please visit <https://fusion.mcelroy.com/parts> to purchase parts or for more information.